



## Portable Appliance Test Certificate

Date	29-09-2023	Sheet	1	of	5
------	------------	-------	---	----	---

Customer Details	<b>Name:</b> St. Albans DJ	<b>Address:</b> 14 Collyer Road, London Colney, St. Albans, Hertfordshire, AL2 1PD			
Contractor Details	<b>Engineer Name:</b> Paul Owen		<b>Contact Number:</b> 01727 5761178 paul@ampedudioservices.com		
Test Equipment	<b>Make:</b> MARTINDALE	<b>Model:</b> HPAT500	<b>Serial Number:</b> 287263138		<b>Date Calibrated:</b> 01/02/2022

Appliance Number	Item Description	Location	Fuse	Earth	Insulation	Visual	Pass/Fail
001	Lead	No Fixed Location		0.05Ω	>200MΩ	Pass	Pass
002	Yamaha Speaker	No Fixed Location			>200MΩ	Pass	Pass
003	Lead	No Fixed Location			>200MΩ	Pass	Pass
005	Lenovo Lead	No Fixed Location			>200MΩ	Pass	Pass
006	Lead	No Fixed Location		0.14Ω	>200MΩ	Pass	Pass
007	Motorola Lead	No Fixed Location			>200MΩ	Pass	Pass
009	Motorola Lead	No Fixed Location			>200MΩ	Pass	Pass
011	Excelvan Projector	No Fixed Location			>200MΩ	Pass	Pass
012	Lead	No Fixed Location			>200MΩ	Pass	Pass
013	Sony Projector	No Fixed Location			>200MΩ	Pass	Pass
014	Extension Lead	No Fixed Location	Pass	0.09Ω	>200MΩ	Pass	Pass
016	Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
019	Wireless Receiver	No Fixed Location			>200MΩ	Pass	Pass
020	LED Bar	No Fixed Location		0.11Ω	>200MΩ	Pass	Pass
021	Lead	No Fixed Location		0.20Ω	>200MΩ	Pass	Pass
023	Lead	No Fixed Location		0.07Ω	>200MΩ	Pass	Pass
024	Lead	No Fixed Location			>200MΩ	Pass	Pass
026	Extension Lead	No Fixed Location	Pass	0.10Ω	>200MΩ	Pass	Pass
027	Extension Lead	No Fixed Location	Pass	0.12Ω	>200MΩ	Pass	Pass
028	Extension Lead	No Fixed Location			>200MΩ	Pass	Pass
033	Pioneer Mixer	No Fixed Location			>200MΩ	Pass	Pass
034	Pioneer CDJ	No Fixed Location			>200MΩ	Pass	Pass
040	Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
041	Starcloth Controller	No Fixed Location		0.08Ω	>200MΩ	Pass	Pass
042	Microbar	No Fixed Location			>200MΩ	Pass	Pass
043	Lead	No Fixed Location		0.16Ω	>200MΩ	Pass	Pass
044	Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass



## Portable Appliance Test Certificate

Date	29-09-2023	Sheet	2	of	5
------	------------	-------	---	----	---

Customer Details	<b>Name:</b> St. Albans DJ	<b>Address:</b> 14 Collyer Road, London Colney, St. Albans, Hertfordshire, AL2 1PD			
Contractor Details	<b>Engineer Name:</b> Paul Owen		<b>Contact Number:</b> 01727 5761178 paul@ampedudioservices.com		
Test Equipment	<b>Make:</b> MARTINDALE	<b>Model:</b> HPAT500	<b>Serial Number:</b> 287263138		<b>Date Calibrated:</b> 01/02/2022

Appliance Number	Item Description	Location	Fuse	Earth	Insulation	Visual	Pass/Fail
045	Lead	No Fixed Location		0.10Ω	>200MΩ	Pass	Pass
046	Lead	No Fixed Location		0.07Ω	>200MΩ	Pass	Pass
047	Equinox Projector	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
048	Lead	No Fixed Location		0.07Ω	>200MΩ	Pass	Pass
049	Gigbar Lighting	No Fixed Location		0.10Ω	>200MΩ	Pass	Pass
051	Yamaha Amp	No Fixed Location			>200MΩ	Pass	Pass
052	Yamaha Amp	No Fixed Location			>200MΩ	Pass	Pass
053	Casio Till	No Fixed Location			>200MΩ	Pass	Pass
054	LED Light	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
055	LED Light	No Fixed Location		0.10Ω	>200MΩ	Pass	Pass
056	Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
059	Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
060	Lead	No Fixed Location		0.10Ω	>200MΩ	Pass	Pass
061	Lead	No Fixed Location			>200MΩ	Pass	Pass
062	Lead	No Fixed Location		0.07Ω	>200MΩ	Pass	Pass
064	Lead	No Fixed Location		0.07Ω	>200MΩ	Pass	Pass
065	Profile Panel	No Fixed Location		0.08Ω	>200MΩ	Pass	Pass
066	Profile Panel	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
068	Lead	No Fixed Location		0.10Ω	>200MΩ	Pass	Pass
069	Spotlight	No Fixed Location			>200MΩ	Pass	Pass
070	Laptop Lead	No Fixed Location			>200MΩ	Pass	Pass
075	Lead	No Fixed Location			>200MΩ	Pass	Pass
076	Lead	No Fixed Location		0.14Ω	>200MΩ	Pass	Pass
077	Lead	No Fixed Location			>200MΩ	Pass	Pass
078	Lead	No Fixed Location		0.06Ω	>200MΩ	Pass	Pass
079	Lead	No Fixed Location		0.10Ω	>200MΩ	Pass	Pass
080	Lead	No Fixed Location		0.15Ω	>200MΩ	Pass	Pass



## Portable Appliance Test Certificate

Date	29-09-2023	Sheet	3	of	5
------	------------	-------	---	----	---

Customer Details	<b>Name:</b> St. Albans DJ	<b>Address:</b> 14 Collyer Road, London Colney, St. Albans, Hertfordshire, AL2 1PD			
Contractor Details	<b>Engineer Name:</b> Paul Owen		<b>Contact Number:</b> 01727 5761178 paul@ampedudioservices.com		
Test Equipment	<b>Make:</b> MARTINDALE	<b>Model:</b> HPAT500	<b>Serial Number:</b> 287263138		<b>Date Calibrated:</b> 01/02/2022

Appliance Number	Item Description	Location	Fuse	Earth	Insulation	Visual	Pass/Fail
081	Extension Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
082	Extension Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
083	Extension Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
085	LED Bar	No Fixed Location		0.12Ω	>200MΩ	Pass	Pass
086	LED Bar	No Fixed Location		0.15Ω	>200MΩ	Pass	Pass
087	Tea Urn	No Fixed Location	Pass	0.19Ω	>200MΩ	Pass	Pass
088	Bass Bin	No Fixed Location		0.13Ω	>200MΩ	Pass	Pass
089	Lead	No Fixed Location			>200MΩ	Pass	Pass
090	Pioneer Controller	No Fixed Location			>200MΩ	Pass	Pass
091	Charger	No Fixed Location			>200MΩ	Pass	Pass
092	Denon Controller	No Fixed Location			>200MΩ	Pass	Pass
093	Mic Receiver Lead	No Fixed Location			>200MΩ	Pass	Pass
096	Video Cam Lead	No Fixed Location			>200MΩ	Pass	Pass
097	Hitachi Proj Lead	No Fixed Location		0.09Ω	>200MΩ	Pass	Pass
098	Hitachi Projector	No Fixed Location		0.13Ω	>200MΩ	Pass	Pass
099	Power Lead	No Fixed Location			>200MΩ	Pass	Pass
100	Power Lead	No Fixed Location			>200MΩ	Pass	Pass
101	Sharp Amp	No Fixed Location			>200MΩ	Pass	Pass
102	Laptop Lead	No Fixed Location			>200MΩ	Pass	Pass
103	Surface Laptop	No Fixed Location			>200MΩ	Pass	Pass
104	Laptop Lead	No Fixed Location			>200MΩ	Pass	Pass
105	Laptop Computer	No Fixed Location			>200MΩ	Pass	Pass
106	Laptop Computer	No Fixed Location			>200MΩ	Pass	Pass
107	Laptop Computer	No Fixed Location			>200MΩ	Pass	Pass
108	CPU/Monitor	No Fixed Location			>200MΩ	Pass	Pass
109	Monitor Pwr Lead	No Fixed Location		0.17Ω	>200MΩ	Pass	Pass
110	Lead	No Fixed Location		0.17Ω	>200MΩ	Pass	Pass



## Portable Appliance Test Certificate

Date	29-09-2023	Sheet	4	of	5
------	------------	-------	---	----	---

Customer Details	<b>Name:</b> St. Albans DJ	<b>Address:</b> 14 Collyer Road, London Colney, St. Albans, Hertfordshire, AL2 1PD			
Contractor Details	<b>Engineer Name:</b> Paul Owen		<b>Contact Number:</b> 01727 5761178 paul@ampedudioservices.com		
Test Equipment	<b>Make:</b> MARTINDALE	<b>Model:</b> HPAT500	<b>Serial Number:</b> 287263138		<b>Date Calibrated:</b> 01/02/2022

Appliance Number	Item Description	Location	Fuse	Earth	Insulation	Visual	Pass/Fail
112	Lead	No Fixed Location		0.12	>200MΩ	Pass	Pass
113	Lead	No Fixed Location		0.12	>200MΩ	Pass	Pass
114	Lead	No Fixed Location			>200MΩ	Pass	Pass
115	Extension Lead	No Fixed Location		0.10	>200MΩ	Pass	Pass
116	Extension Lead	No Fixed Location		0.13	>200MΩ	Pass	Pass
117	Extension Lead	No Fixed Location		0.13	>200MΩ	Pass	Pass
118	Denon Controller	No Fixed Location			>200MΩ	Pass	Pass
119	Extension Lead	No Fixed Location		0.07	>200MΩ	Pass	Pass
120	Mic Controller	No Fixed Location			>200MΩ	Pass	Pass
121	Studio Mixer	No Fixed Location		0.09	>200MΩ	Pass	Pass
122	Power Lead	No Fixed Location			>200MΩ	Pass	Pass
123	Lead	No Fixed Location		0.14	>200MΩ	Pass	Pass
124	Lead	No Fixed Location		0.09	>200MΩ	Pass	Pass
125	Lead	No Fixed Location		0.09	>200MΩ	Pass	Pass
126	Lead	No Fixed Location		0.09	>200MΩ	Pass	Pass
127	Lead	No Fixed Location		0.15	>200MΩ	Pass	Pass
128	Mood Light	No Fixed Location			>200MΩ	Pass	Pass
129	Mood Light	No Fixed Location			>200MΩ	Pass	Pass
130	Mood Light	No Fixed Location			>200MΩ	Pass	Pass
131	Mood Light	No Fixed Location			>200MΩ	Pass	Pass
132	Mood Light	No Fixed Location			>200MΩ	Pass	Pass
133	Mood Light	No Fixed Location			>200MΩ	Pass	Pass
134	Extension Lead	No Fixed Location			>200MΩ	Pass	Pass
135	Extension Lead	No Fixed Location			>200MΩ	Pass	Pass
136	Lead	No Fixed Location		0.07	>200MΩ	Pass	Pass
137	Extension Lead	No Fixed Location		0.09	>200MΩ	Pass	Pass
138	LED Bar	No Fixed Location			>200MΩ	Pass	Pass



## Portable Appliance Test Certificate

Date	29-09-2023	Sheet	5	of	5
------	------------	-------	---	----	---

Customer Details	<b>Name:</b> St. Albans DJ	<b>Address:</b> 14 Collyer Road, London Colney, St. Albans, Hertfordshire, AL2 1PD			
Contractor Details	<b>Engineer Name:</b> Paul Owen		<b>Contact Number:</b> 01727 5761178 paul@ampedudioservices.com		
Test Equipment	<b>Make:</b> MARTINDALE	<b>Model:</b> HPAT500	<b>Serial Number:</b> 287263138		<b>Date Calibrated:</b> 01/02/2022

Appliance Number	Item Description	Location	Fuse	Earth	Insulation	Visual	Pass/Fail
139	LED Bar	No Fixed Location			>200MΩ	Pass	Pass
140	LED Bar	No Fixed Location			>200MΩ	Pass	Pass
141	LED Bar	No Fixed Location			>200MΩ	Pass	Pass

\* Fuse & Earth results have been entered where obtainable by test equipment. Absence of these values does NOT constitute a Failed test.